

HOLYHEAD – Marine Safety & Information Circular 06/2025

Terminal 5 5F Berth Line Fender

Issued 25th March 2025 Expires Until advised

Please be advised that the torsion arms on 5F fender pile have been removed as have the smaller Yokohama fenders.

A replacement 3.3-meter x 6.5-meter Yokohama fender has been installed at 5F on the berth line.

The Yokohama fender has been installed by utilising an existing securing point at the base of the concrete platform.


Wire rope is secured to a two-ton sinker on the seabed at the north corner of the dolphin laying at the foot of the pile and not laying off.

We anticipate that the Yokohama fender will now rise and fall on the tide and remain in position.


Please see below photographs for further information.

Michael Coates Deputy Harbour Master Port of Holyhead Stena Line Ports Ltd Holyhead Harbour Authority

































Sent from my iPhone

Stena Line Ports Ltd Holyhead Harbour Authority



Michael Coates Deputy Harbour Master Port of Holyhead